

01 143Z 11 AUG 63

SECRET

TO DIRECTOR

OPS 1-7

TOE 1309Z 11 AUG 63

86821

LOGS

027

A. 6056

B. 358

C. 11 AUG 63 8 PLUS 25

D. HQS DIRECTED MISSION WITH

E. AND COCKPIT PRESS FLUCTUATION

CORR ACTION: PENDING FURTHER INVESTIGATION

2) SEXTANT REFLECTED A DOUBLE IMAGE

CORR ACTION: PENDING FURTHER INVESTIGATION

3) MACH SENSOR OSCILLATION OF .5 KTS AT HIGH POWER SETTINGS.

CORR ACTION: ADJUST MACH AMP.

25 YEAR RE-REVIEW

F. NEGATIVE

G. NEGATIVE

END OF MESSAGE

SECRET